

## ROCKY FLATS ENVIRONMENTAL TECHNOLOGY SITE ER REGULATORY CONTACT RECORD

---

**Date/Time:** April 11, 2006

**Site Contact(s):** Laura Brooks; Rick DiSalvo  
**Phone:** 303-966-6130; 303-966-4785

**Regulatory Contact:** Mark Aguilar, USEPA; Carl Spreng and Dave Kruchek, CDPHE  
**Phone:** 303-312-6251; 303-692-3358; 303-692-3328

**Agency:** USEPA and CDPHE

---

**Purpose of Contact:** Documentation of Final Facility Disposition under RFCA for K750, K771, B133, B559A, S372, S444, S460, B709A, T690N, B980 and B123/123S

---

### Discussion

Some small buildings, for example, guard shacks, portable shelters, bus stop enclosures, etc., were not formally typed during decommissioning under the Rocky Flats Cleanup Agreement (RFCA), but met Type 1 criteria. Using the consultative process, these small buildings were determined to be structures or equipment and were dispositioned using the Rocky Flats Environmental Technology Site (RFETS) Property/Waste Release Evaluation process rather than using the decommissioning Reconnaissance Level Characterization (RLC)/Pre-Demolition Survey (PDS) process. This contact record shall be filed in the Administrative Record (AR) File for each of the buildings identified below, and the RI/FS Report shall indicate that the consultative process was used for determining the appropriate disposition.

The following buildings were dispositioned as uncontaminated, similar to Type 1 buildings, and complete RLC Report and informational closeout reports were not required.

- K750 and K771 (skid mounted shacks) - Based on Historical Site Assessment Reports preliminary information for these items, these were small portable buildings (skid mounted shacks) and formal typing and closeout report was not prepared.
- B133 (130 guard post)
- 559A (Accountability Board shelter)
- S372 (Bus stop car pool shelter)
- S444 (Bus stop car pool shelter)
- S460 (Portable Shelter/Bus Stop)
- 709A was an emergency diesel pump for the B 707 Cooling tower. B 709 was Type 1, so 709A is also considered Type 1.
- T690N was an office trailer, and the Typing, based on the RLCR, was concurred with as a Type 1. An informational close out report was not prepared.

The following Type 2 buildings did not have approved Closeout Reports, but it was agreed that the buildings were properly dispositioned and the Closeout Reports are approved.

- 980 – This building was dispositioned prior to formal RFCA Typing, but was contaminated and would have been Type 2. Closeout Report (B980-A-000006) is in the AR File, but may not have been formally transmitted. The slab was separately dispositioned and the Closeout for the slab (B980-A- 000023) was approved (B980-A 000042), so the review and approval basically encompasses any issues that would have remained for B980. CDPHE is the LRA and agrees that the building was properly dispositioned.
- 123/123S - Closeout Report (B123-A-000108) was submitted to CDPHE; however no formal approval was received based on review of AR File and Correspondence Control database. CDPHE is the LRA and agrees that the building was properly dispositioned.

---

**Contact Record Prepared By: Laura Brooks**

---

Distribution:

M. Aguilar, USEPA  
L. Kimmel, USEPA  
J. Berardini, K-H Legal  
L. Brooks, K-H  
R. Schassburger, DOE-RFFO  
N. Castaneda, DOE-RFFO  
C. Deck, K-H Legal  
C. Spreng, CDPHE  
S. Surovchak, DOE-RFFO  
D. Kruchek, CDPHE  
J. Walstrom, K-H  
C. Zahm, K-H Legal

